

SWIMMING POOL OFFICIAL INSPECTION REPORT

Facility Name WALNUT COMMUNITY Address 3510 BEACON AVE. City FREMONT
 Owner/Operator _____ Business Phone _____

OBSERVATIONS AND CORRECTIVE ACTIONS

SR #40327 - FINAL INSPECTION (Approved)

POOL pH 7.5
* Chlorine 14.0 ppm (Maintain between 2.0 ~ 10.0 max ppm)
CYA 35 ppm
Influent 18 psi
Effluent 10 psi
Flow Rate 90 gpm

SPA pH 7.4
Chlorine 10.0 ppm
CYA 100 ppm (Not to exceed 100 ppm)
Influent 22 psi
Effluent 16 psi
Flow Rate 75 gpm

Pool Enclosure, signs, safety tools, skimmers, pump, filters, under water light and GFCI checked OK.

Spa emergency shut-off, skimmers, pump, filter, underwater light and GFCI checked OK.

All items noted on the 9-12-2022 inspection report have been corrected, except pool chlorine exceeded max limit of 10.0 ppm and restroom floor still require proper covered base. Comply within 30 days.

Facility is approved to apply for pool/spa permits.

Complete permit application and email it to <jean.chen@acgov.org> (verb certification received.)

- REINSPECTION REQUIRED - NOTE:** A fee \$ _____ will be charged for each reinspection as authorized by current County ordinance and is due 30 days after billing.
- POOL/SPA CLOSURE:** THIS POOL IS HEREBY CLOSED BY THE DEPARTMENT OF ENVIRONMENTAL HEALTH. IT IS TO REMAIN CLOSED UNTIL REOPENED BY THIS DEPARTMENT. (GATES MUST BE CLOSED AND LOCKED.)

Environmental Health Specialist: <u>Janchen</u>	Phone: (510) <u>567-6844</u>	Date: <u>9-15-2022</u>
Received by: <u>Wagdi Hakkar</u>	Title: <u>APM</u>	Time In: <u>3:25 pm</u> Time out: _____